

SERVICE BULLETIN


Subject: Incorrect Vector Global Audio Wiring Diagram

Date: 5/2/05


Distribution: Vector Scorer Customers

Bulletin No. SB05-4

It has come to our attention that the Global Audio wiring diagram on page 56 of the Vector Scorer Service Manual, part number 57-900621-000, is incorrect. Figure 1 shows the incorrect diagram and Figure 2 shows the correct diagram.



*Incorrect Diagram
Figure 1*



Correct Diagram
Figure 2

If you have questions regarding this or any other Service Bulletin, please contact the Brunswick Customer Response Center at 1-800-323-8141 or 231-725-4966, FAX 231-725-4667, or E-mail http://www.brunswickbowling.com/contact_us

Kord L. Daniels

Kord L. Daniels
Service Product Engineer

David E. Rice

David E. Rice
Director of Worldwide Service