

SERVICE BULLETIN

Subject: AMF 8290 Pinspotter Electronics Identification

Date: 9/21/12

Bulletin No. SB12-7

This document is intended to provide the information necessary for personnel to make an informed decision regarding the types of AMF 8290 pinspotter electronics a center has and the type of scoring interface required.

It has come to our attention that there is some confusion with the different types of AMF 8290 pinspotter electronics.

8290XL Upgrade Chassis

The 8290XL upgrade is an 8270 pinspotter upgraded to 8290XL, also called an 8800. From the information we have, the 8290XL upgrade and 8800 are the same. This version of the 8290XL chassis began production in 1993. Refer to Figures 1 & 2.




Figure 1 - Front of 8290XL Upgrade Chassis




Figure 2 - Back of 8290XL Upgrade Chassis

8290XL Silver Chassis

The 8290XL Silver Chassis is a new pinspotter and electronics installation. This version of the 8290XL chassis began production in 1996. Refer to Figures 3 & 4.




Figure 3 - Front of Silver Box 8290XL Chassis




Figure 4 - Back of Silver Box 8290XL Chassis

8290XL Black Chassis

The 8290XL black chassis is a new pinspotter and electronics installation. This version of the 8290XL chassis began production in 2003. Refer to Figures 5 & 6.




Figure 5 - Front of Black Box 8290XL Chassis




Figure 6 - Back of Black Box 8290XL Chassis

8290XLi Chassis

The 8290XLi chassis is a new pinspotter and electronics installation or can be an upgrade installation also. This version of the 8290XLi chassis started production in 2006. The 8290XLi is also the chassis used on the new Edge pinspotter. Refer to Figures 7 & 8.




Figure 7 - Front of 8290XLi Chassis




Figure 8 - Back of 8290XLi Chassis

If you have questions regarding the information contained in this Service Bulletin, please contact Brunswick Technical Support at 1-800-937-2695 or 231-725-4966, FAX 231-725-4667, or Email techsupport@brunbowl.com Visit <http://www.brunswickbowling.com/service-support/tech-support/> for electronic files of this and other Service Bulletins.

Kord L. Daniels
 Kord L. Daniels
 Service Product Engineer

David E. Rice
 David E. Rice
 Director of World Wide Service