

SERVICE BULLETIN

Subject: GS-Series Pinsetter Switch Setting


Date: 2/18/99

Distribution: GS-Series Pinsetter Customers

Letter No. CEB99-2


All GS-Series pinsetters have DIP switches that allow mechanics to configure the machine for numerous operating environments. If your center must comply with ABC/WIBC/FIQ regulations, you should verify the setting of switch 6 of the Lane Assignment DIP switch.

This switch determines if there will be a delay of the setting table after the sweep drops to the guarded position. To conform with ABC/WIBC/FIQ specifications, the switch must be set to the "ON" position.



Additionally, centers that have pinsetters with consolidated electronics may, on occasion, experience a problem during a short cycle where the sweep is not raised to the up position. Setting switch 6 to the "ON" position will typically correct this situation.

If you have any questions concerning the switch setting, please contact Brunswick's Customer Response Center at 1.800.323.8141.


Bill Jager
Service Product Engineer


David E. Rice
Director of Service and Installation