

Pinsetter Frame Mount Photosensor Reset




Figure 1

Mount Safety Mirror





Figure 2